

Pad-Mounted Gear Inspection Program Helps Utility Manage Aging Assets

S&C Featured Solution: S&C's Power Systems Solutions

Location: Southeast United State

Customer Challenge

Expanding upon an existing program to externally inspect the condition of their pad-mounted switchgear, a large investor-owned electric utility in the southeastern United States outsourced the comprehensive internal and external inspection of its entire installed base of 1,800 pad-mounted gear units to S&C. Performed with the gear energized, the objective of the inspection program was to develop a prioritized approach to maintenance, which would ultimately extend the life of the gear, reduce outages, and increase system reliability.

S&C Solution

S&C's Power Systems Solutions personnel worked with the utility to create a customized, detailed inspection list that included the switchgear manufacturer's inspection procedures, supplemented by the utility's own practices.

A two-person team of expert S&C field technicians was dedicated to the inspection of all pad-mounted gear on the utility's distribution system. They coordinated their efforts with the utility's load dispatchers daily. The crew used the inspection list to record observations and maintenance recommendations for each unit of

| PAD-MOUNTED-GEAR INSPECTIONS CHECKLIST
| General Information:
| 1. Manufacture:
| 2. Type or model of gaz:
| 3. Calsing number:
| 4. Settal number:
| 5. Manufacture: date:
| 6. Nearest street address:
| 7. Location 8 |
| 1. Interior Inspections:
| (Note details of abnormal conditions in comments section)
1. Structural integrit of gaz: good	file	poor	
2. Condensation: none	present	conditions	poor
3. Instruction date	particular	file	file
4. Words: Y C N			
5. Instruction Conditions: good	damaged	tracking	dirty
6. Calso termination conditions: good	damaged	first	corruston
7. Settic (Conditions: good	damaged	first	corruston
8. Pas budder conditions: good	damaged	first	corruston
8. Pas budder conditions: good	damaged	first	corruston
9. Part introductor conditions: good	damaged	first	corruston
10. The conditions good	damaged	first	corruston
11. Prieper characters between burders and corregisted parts: Y	N		
12. Cards excent healted properly (if application)	Y	N	Cardinary
13. Recommendation	first	corruston	
14. Description	first	corruston	
15. Brance conditions: good	damaged	first	corruston
16. Calso teamination required	first	corruston	
17. Rate level of Attention required			
18. Comments			
19. Action	first	firs	

gear, including conformance with the manufacturer's installation instructions. Of particular concern were:

- Insufficient terminator-barrier clearance
- Damaged terminators
- · Gear improperly positioned on its concrete pad
- Gear with access limited by vegetation
- Missing padlocks

The crew also developed a prioritization report to identify the switchgear units requiring greatest attention. Gear needing urgent attention was immediately reported to the utility.

Results

In less than a year, S&C inspected all 1,800 padmounted gear units. While the vast majority of the equipment was manufactured by S&C, the inspection program included an assessment of gear manufactured by other suppliers, too.

The utility is very pleased with the information collected and has expanded the maintenance program to other equipment. It has contracted with S&C for the inspection of 850 pad-mounted transformers serving critical loads. The next round of pad-mounted gear inspections has been scheduled for 2008.

